

## Junction Box Mounting with GV-Mount512




### Packing List

1. GV-Mount512 Junction Box	2. Screw (4 x 10 mm) x 3
3. Screw (4 x 25 mm) x 4	4. Screw Waterproof Ring x 4
5. Plastic Anchor (6 x 29 mm) x 4	6. Drill Template Paster

### Applicable Models

- GV-GFER6900 / GFER12800


### Dimensions




## Installation

The steps below show an example installation of **GV-GFER6900** using **GV-Mount512**.


1. Remove the trim ring from the gap of the camera.



2. Install the junction box onto the wall.



3. Route the cables through the cable hole (take side conduit cabling for example) and connect the cables. Then fasten the camera onto the junction box with screws.



4. Install the trim ring back to finish the installation.

